

Enclosure 2: Pictures of Texas Township Wetland Comparisons.

The 20 acre wetlands that are recipients of the Eagle/Crooked Lake pumping discharge is shown below. EGLE decision is based on this wetland property showing stress.



8TH ST. AT BENTWOOD

Other wetlands in Texas Township that have been impacted by flooding are shown on the following pages. The stress on these wetlands is evident in these photos, as well as showing large trees being impacted.



CORNER 3RD ST. & P AVE.



7694 WEST S AVE.



TREASURE ISLAND
CAUSWAY



Q AVE. BETWEEN 5TH ST. AND 3RD ST.



O AVE. CLOSED DUE TO HIGH WATER



11055 8TH ST. NEAR U AVE. WITH BARRICADES BY COUNTY ROAD COMMISSION